This Standard is Being Changed Due to the ARC Report to ORR

STANDARD	RULE NUMBERS	MIOSHA IMPLEMENTATION STRATEGY
CS Part 12 Scaffold and Scaffold Platforms	R 408.41210	The requirement for lumber standards will be addressed by Rules 1217, 1210(8), or a general duty violation with reference to the applicable ANSI Standard.
	R 408.41211	The hazards associated with the rescinded rule will be addressed by Rule 1217(9).
Effective April 11, 2013	R 408.41215	The hazards associated with the rescinded rules will be addressed by Rules 1214(1) and 1214(3).
Strike-Bold	R 408.41217	The hazards associated with the rescinded rules will be addressed by Rules 1217(1), 1217(5) and 2159(1).
	R 408.41221	The hazards associated with the rescinded rules will be addressed by Rule 1210(3).
	R 408.41222	The hazards associated with the rescinded rule will be addressed by Rule 1210(8) and Appendix A.
	R 408.41224	The hazards associated with the rescinded rule will be addressed by Rules 1210(1) and 1210(3).
	R 408.41225	The rules for horse scaffolds were amended to the OSHA equivalent.
	R 408.41226	The rules for bricklayer's square scaffolds were amended to the OSHA equivalent.
	R 408.41227	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1217(1).
	R 408.41228	The hazards associated with the rescinded rules will be addressed by Rules 1210(1) and 1210(3).
	R 408.41231	The hazards associated with the rescinded rules will be addressed by Rules 1229(2), 1229(3), and 1229(15)(e).
	R 408.41233	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1210(6).
	R 408.41234	The hazards associated with the rescinded rules will be addressed by Rules 1213(3) and 1210(3).
	R 408.41235	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1229(17)
	R 408.41236	The hazards associated with the rescinded rules will be addressed by Rules 1210(3), 1217(1), and 1219(2).
	R 408.41237	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1213(3).
	R 408.41243	The hazards associated with the rescinded rules will be addressed by Rules 1243(2), 114(2) and 123.
	R 408.41244	The hazards associated with the rescinded rules will be addressed by Rules 114(2) and 115(2)(a).
	R 408.41245	The hazards associated with the rescinded rule will be addressed by Rule 114(2).
	R 408.41246	The requirement for operator training will be addressed by Part 13, Mobile Equipment.
	R 408.41253	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1217(7).
	R 408.41254	The rules for carpenter bracket scaffolds were amended to the OSHA equivalent.
	R 408.41255	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1217(1).

STANDARD	RULE NUMBERS	MIOSHA IMPLEMENTATION STRATEGY
	R 408.41256	The hazards associated with the rescinded rules will be addressed by Rules 1210(3), 1217(1) and 1217(5).
CS Part 12 Scaffold and Scaffold Platforms	R 408.41261	The hazards associated with the rescinded rules will be addressed by Rules 1210(1), 1210(3), 1261(1), 1229(18) and 834(4).
	R 408.41262	The hazards associated with the rescinded rules will be addressed by Rules 114(2)(c), 1210(3), and 1210(6).
	R 408.41263	The hazards associated with the rescinded rules will be addressed by Rules 114(2)(c), 1210(3), and 1210(6).
	R 408.41264	The hazards associated with the rescinded rules will be addressed by Rules 1210(3) and 1213(1).
	Appendix A	A new appendix was added to be equivalent to OSHA.